4655 South Columbia Ave. Tulsa, OK 74105

Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

Insured: Paul Greene

Property: 301 Ridgecrest Court

Bartlesville, OK 74006

Claim Rep.: Len Lenard Business: (940) 594-0821

Estimator: Matt Clark Business: (409) 350-1440

Position: Estimator

Company: Ark Consultants

Claim Number: 3606L748B Policy Number: 36CEV1197 Type of Loss: <NONE>

Date of Loss: Date Received:

Date Inspected: Date Entered: 7/8/2021 5:35 PM

Price List: OKTU8X_JUN21

Restoration/Service/Remodel

Estimate: VC-301RIDGECREST

This is a preliminary estimate for discussion purposes only. We do hold the right to change or replace this estimate based on damages, code, repair method and any additional information that may come available.

4655 South Columbia Ave. Tulsa, OK 74105 Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

VC-301RIDGECREST

Roof

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
1. Laminated - comp. shingle rfg w/ felt	32.95 SQ	48.37	0.00	318.76	1,912.55	(0.00)	1,912.55
2. Laminated - comp. shingle rfg w/ felt	38.00 SQ	227.02	491.54	1,823.66	10,941.96	(0.00)	10,941.96
3. Asphalt starter - peel and stick	303.58 LF	1.91	24.44	120.84	725.12	(0.00)	725.12
4. Step flashing	45.08 LF	8.23	7.98	75.80	454.79	(0.00)	454.79
5. Drip edge/gutter apron	303.58 LF	2.57	35.96	163.24	979.40	(0.00)	979.40
6. Roof vent - turtle type - Metal	8.00 EA	57.35	14.88	94.74	568.42	(0.00)	568.42
7. Flashing - pipe jack - lead	8.00 EA	77.45	42.61	132.44	794.65	(0.00)	794.65
8. Ridge cap - composition shingles	52.17 LF	5.56	6.24	59.24	355.54	(0.00)	355.54
9. Continuous ridge vent - shingle-over style	50.00 LF	8.41	20.13	88.12	528.75	(0.00)	528.75
10. Digital satellite system - Detach & reset	1.00 EA	34.34	0.00	6.86	41.20	(0.00)	41.20
Totals: Roof			643.78	2,883.70	17,302.38	0.00	17,302.38

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
11. Gutter / downspout - aluminum - up to 5"	172.00 LF	6.95	72.99	253.68	1,522.07	(0.00)	1,522.07
12. Exterior double door - alder - paneled	1.00 EA	1,828.66	189.90	403.72	2,422.28	(0.00)	2,422.28
13. Exterior door - solid alder - paneled - slab only	1.00 EA	807.69	81.08	177.76	1,066.53	(0.00)	1,066.53
14. Vinyl inside corner post	72.50 LF	5.30	14.34	79.72	478.32	(0.00)	478.32
15. Vinyl outside corner post	123.83 LF	6.15	36.60	159.64	957.79	(0.00)	957.79
16. Vinyl J trim	486.00 LF	3.65	37.45	362.28	2,173.63	(0.00)	2,173.63
17. Fascia - metal - 6"	106.08 LF	4.64	22.81	103.00	618.02	(0.00)	618.02
18. Wrap custom fascia with aluminum (PER LF)	197.50 LF	12.50	49.97	503.76	3,022.48	(0.00)	3,022.48
19. Soffit - vinyl	394.00 SF	4.90	97.87	405.70	2,434.17	(0.00)	2,434.17
20. Siding - vinyl	3,557.00 SF	0.38	0.00	270.34	1,622.00	(0.00)	1,622.00
21. Rigid foam insulation board - 3/4"	3,557.00 SF	1.09	216.80	818.78	4,912.71	(0.00)	4,912.71
22. Siding - vinyl	3,914.00 SF	3.55	792.19	2,937.38	17,624.27	(0.00)	17,624.27
23. Clean stone veneer	654.00 SF	0.83	2.26	109.02	654.10	(0.00)	654.10
24. Surveillance camera - color	1.00 EA	44.29	0.00	8.86	53.15	(0.00)	53.15
25. Surveillance camera - color	1.00 EA	586.65	46.00	126.54	759.19	(0.00)	759.19
26. Light fixture - wall sconce	5.00 EA	50.26	0.00	50.26	301.56	(0.00)	301.56
27. Hanging light fixture	1.00 EA	50.26	0.00	10.06	60.32	(0.00)	60.32
28. Spot light fixture - double - w/motion sensor	2.00 EA	74.62	0.00	29.84	179.08	(0.00)	179.08

4655 South Columbia Ave. Tulsa, OK 74105

Phone | 972.266.4950


Missing Wall

Email | Brook@claimadvisorsllc.com

CONTINUED - Exterior

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
29. Wood fence - board on board - 5'- 6' high - treated	405.00 LF	37.68	962.71	3,244.62	19,467.73	(0.00)	19,467.73
30. Tree - removal - 12" to 24" diameter / large canopy	4.00 EA	999.66	0.00	799.72	4,798.36	(0.00)	4,798.36
31. Stone veneer - natural stone	150.00 SF	46.31	6.73	1,390.64	8,343.87	(0.00)	8,343.87
Stone Wall Around Pool							
32. Pool Repair Estimate (Beauty-Crete Inc.)*	1.00 EA	11,302.00	0.00	0.00	11,302.00	(0.00)	11,302.00
33. Repair Deck Estimate (Beauty-crete Inc)*	1.00 EA	29,961.00	0.00	0.00	29,961.00	(0.00)	29,961.00
Totals: Exterior			2,629.70	12,245.32	114,734.63	0.00	114,734.63

1st Floor



14' 1" X 8'

Opens into DINING_AREA
Opens into DINING_AREA

Height: 8'

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Ceiling							
34. 5/8" drywall - hung, taped, ready for texture	302.83 SF	2.13	20.90	133.20	799.13	(0.00)	799.13
35. Texture drywall - light hand texture	302.83 SF	0.47	1.74	28.80	172.87	(0.00)	172.87
36. Seal floor or ceiling joist system	302.83 SF	1.02	7.66	63.32	379.87	(0.00)	379.87
Per Benjamin Moore Proper Application in	ncludes; Clean Su	urface, Prime Surfa	ce, and Two C	oats Of Topcoa	at		
37. Clean the ceiling	302.83 SF	0.33	0.35	20.06	120.34	(0.00)	120.34
38. Seal the ceiling w/latex based stain blocker - one coat	302.83 SF	0.50	2.44	30.76	184.62	(0.00)	184.62
39. Paint the ceiling - two coats	302.83 SF	0.80	6.97	49.86	299.09	(0.00)	299.09
40. Ceiling fan & light	1.00 EA	178.98	0.00	35.80	214.78	(0.00)	214.78
Wall							
41. Crown molding - 3 1/4"	49.39 LF	4.29	8.29	44.02	264.19	(0.00)	264.19

4655 South Columbia Ave. Tulsa, OK 74105 Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

CONTINUED - Living Room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
42. Seal & paint crown molding - two coats	49.39 LF	1.25	0.74	12.48	74.96	(0.00)	74.96
43. Batt insulation - 4" - R15 - paper / foil faced	395.12 SF	1.28	35.90	108.32	649.98	(0.00)	649.98
44. 1/2" drywall - hung, taped, ready for texture	395.12 SF	2.01	23.63	163.56	981.38	(0.00)	981.38
45. Texture drywall - light hand texture	395.12 SF	0.47	2.27	37.60	225.58	(0.00)	225.58
46. Seal stud wall for odor control	395.12 SF	0.73	7.72	59.22	355.38	(0.00)	355.38
Per Benjamin Moore Proper Application in	cludes; Clean S	urface, Prime Surf	face, and Two	Coats Of Topo	oat		
47. Clean the walls	395.12 SF	0.33	0.45	26.18	157.02	(0.00)	157.02
48. Seal the walls w/latex based stain blocker - one coat	395.12 SF	0.50	3.18	40.16	240.90	(0.00)	240.90
49. Paint the walls - two coats	395.12 SF	0.80	9.09	65.04	390.23	(0.00)	390.23
50. Paint door or window opening - 2 coats (per side)	3.00 EA	25.52	1.40	15.60	93.56	(0.00)	93.56
51. Seal & paint window sill	12.00 LF	2.09	0.32	5.08	30.48	(0.00)	30.48
52. Window blind - single cell - 7.1 to 14 SF	3.00 EA	28.79	0.00	17.28	103.65	(0.00)	103.65
53. Baseboard - 3 1/4"	49.39 LF	3.30	6.99	34.00	203.98	(0.00)	203.98
54. Paint baseboard - two coats	49.39 LF	1.18	0.68	11.80	70.76	(0.00)	70.76
55. Ceramic/porcelain tile	144.00 SF	10.98	73.03	330.82	1,984.97	(0.00)	1,984.97
Around the fireplace							
Floor							
56. Carpet	302.83 SF	0.24	0.00	14.54	87.22	(0.00)	87.22
57. Carpet pad	302.83 SF	0.67	16.72	43.92	263.53	(0.00)	263.53
58. Carpet	369.83 SF	3.34	114.41	269.92	1,619.56	(0.00)	1,619.56
59. Final cleaning - construction - Residential	302.83 SF	0.24	0.00	14.54	87.22	(0.00)	87.22
Totals: Living Room			344.88	1,675.88	10,055.25	0.00	10,055.25

4655 South Columbia Ave.

Tulsa, OK 74105 Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com



DIning Area

Height: 8'

290.88 SF Walls 460.76 SF Walls & Ceiling 18.88 SY Flooring 36.36 LF Ceil. Perimeter

169.88 SF Ceiling169.88 SF Floor36.36 LF Floor Perimeter

Missing Wall
Missing Wall
Missing Wall

5' 4 15/16" X 8' 7' 1" X 8' 14' 1" X 8' Opens into LIVING_ROOM Opens into HALLWAY2 Opens into LIVING_ROOM

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Ceiling							
60. 5/8" drywall - hung, taped, ready for texture	169.88 SF	2.13	11.72	74.72	448.29	(0.00)	448.29
61. Texture drywall - light hand texture	169.88 SF	0.47	0.98	16.16	96.98	(0.00)	96.98
62. Seal floor or ceiling joist system	169.88 SF	1.02	4.30	35.52	213.10	(0.00)	213.10
Per Benjamin Moore Proper Application in	cludes; Clean S	urface, Prime Surf	ace, and Two	Coats Of Topo	coat		
63. Clean the ceiling	169.88 SF	0.33	0.20	11.26	67.52	(0.00)	67.52
64. Seal the ceiling w/latex based stain blocker - one coat	169.88 SF	0.50	1.37	17.26	103.57	(0.00)	103.57
65. Paint the ceiling - two coats	169.88 SF	0.80	3.91	27.96	167.77	(0.00)	167.77
66. Hanging light fixture	1.00 EA	50.26	0.00	10.06	60.32	(0.00)	60.32
Wall							
67. Crown molding - 3 1/4"	36.36 LF	4.29	6.11	32.42	194.51	(0.00)	194.51
68. Seal & paint crown molding - two coats	36.36 LF	1.25	0.54	9.20	55.19	(0.00)	55.19
69. Batt insulation - 4" - R15 - paper / foil faced	290.88 SF	1.28	26.43	79.74	478.49	(0.00)	478.49
70. 1/2" drywall - hung, taped, ready for texture	290.88 SF	2.01	17.39	120.40	722.46	(0.00)	722.46
71. Texture drywall - light hand texture	290.88 SF	0.47	1.67	27.68	166.06	(0.00)	166.06
72. Seal stud wall for odor control	290.88 SF	0.73	5.69	43.60	261.63	(0.00)	261.63
Per Benjamin Moore Proper Application in	cludes; Clean S	urface, Prime Surf	ace, and Two	Coats Of Topo	coat		
73. Clean the walls	290.88 SF	0.33	0.33	19.26	115.58	(0.00)	115.58
74. Seal the walls w/latex based stain blocker - one coat	290.88 SF	0.50	2.34	29.54	177.32	(0.00)	177.32
75. Paint the walls - two coats	290.88 SF	0.80	6.69	47.88	287.27	(0.00)	287.27
76. Paint door slab only - 2 coats (per side)	3.00 EA	30.60	2.34	18.82	112.96	(0.00)	112.96
77. Paint door or window opening - 2 coats (per side)	s 3.00 EA	25.52	1.40	15.60	93.56	(0.00)	93.56
78. Seal & paint window sill	3.00 LF	2.09	0.08	1.28	7.63	(0.00)	7.63
79. Window blind - single cell - 7.1 to 14 SF	1.00 EA	28.79	0.00	5.76	34.55	(0.00)	34.55
80. Baseboard - 3 1/4"	36.36 LF	3.30	5.14	25.02	150.15	(0.00)	150.15
81. Paint baseboard - two coats	36.36 LF	1.18	0.50	8.68	52.08	(0.00)	52.08


4655 South Columbia Ave. Tulsa, OK 74105

Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

CONTINUED - DIning Area

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Floor							
82. Pre-finished solid wood flooring	169.88 SF	10.77	104.13	386.76	2,320.50	(0.00)	2,320.50
83. Add for glued down application over concrete substrate	169.88 SF	2.48	17.00	87.66	525.96	(0.00)	525.96
84. Final cleaning - construction - Residential	169.88 S F	0.24	0.00	8.16	48.93	(0.00)	48.93
Totals: DIning Area			220.26	1,160.40	6,962.38	0.00	6,962.38



Hallway Height: 8'

232.69 SF Walls 328.21 SF Walls & Ceiling

10.61 SY Flooring29.09 LF Ceil. Perimeter

95.52 SF Ceiling 95.52 SF Floor 29.09 LF Floor Perimeter

Missing Wall 5' 11 5/8" X 8'
Missing Wall 7' 1" X 8'

Opens into ENTRY2
Opens into DINING_AREA

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Ceiling							
Per Benjamin Moore Proper Application in	cludes; Clean S	urface, Prime Surfac	ce, and Two Co	oats Of Topco	at		
85. Clean the ceiling	95.52 SF	0.33	0.11	6.32	37.95	(0.00)	37.95
86. Seal the ceiling w/latex based stain blocker - one coat	95.52 SF	0.50	0.77	9.72	58.25	(0.00)	58.25
87. Paint the ceiling - two coats	95.52 SF	0.80	2.20	15.72	94.34	(0.00)	94.34
88. Hanging light fixture	1.00 EA	50.26	0.00	10.06	60.32	(0.00)	60.32
Wall							
89. Crown molding - 3 1/4"	29.09 LF	4.29	4.88	25.94	155.61	(0.00)	155.61
90. Seal & paint crown molding - two coats	29.09 LF	1.25	0.43	7.36	44.15	(0.00)	44.15
Per Benjamin Moore Proper Application in	cludes; Clean S	urface, Prime Surfac	ce, and Two Co	oats Of Topco	at		
91. Clean the walls	232.69 SF	0.33	0.27	15.42	92.48	(0.00)	92.48
92. Seal the walls w/latex based stain blocker - one coat	232.69 SF	0.50	1.87	23.66	141.88	(0.00)	141.88
93. Paint the walls - two coats	232.69 SF	0.80	5.35	38.32	229.82	(0.00)	229.82
94. Paint door slab only - 2 coats (per side)	1.00 EA	30.60	0.78	6.28	37.66	(0.00)	37.66


4655 South Columbia Ave. Tulsa, OK 74105

Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

CONTINUED - Hallway

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
95. Paint door or window opening - 2 coats (per side)	1.00 EA	25.52	0.47	5.20	31.19	(0.00)	31.19
96. Baseboard - 3 1/4"	29.09 LF	3.30	4.11	20.02	120.13	(0.00)	120.13
97. Paint baseboard - two coats	29.09 LF	1.18	0.40	6.94	41.67	(0.00)	41.67
Floor							
98. Pre-finished solid wood flooring	95.52 SF	10.77	58.55	217.48	1,304.78	(0.00)	1,304.78
99. Add for glued down application over concrete substrate	95.52 SF	2.48	9.56	49.30	295.75	(0.00)	295.75
100. Final cleaning - construction - Residential	95.52 SF	0.24	0.00	4.58	27.50	(0.00)	27.50
Totals: Hallway			89.75	462.32	2,773.48	0.00	2,773.48



Entry

130.33 SF Walls182.55 SF Walls & Ceiling

5.80 SY Flooring

16.29 LF Ceil. Perimeter

52.22 SF Ceiling

52.22 SF Floor

16.29 LF Floor Perimeter

Height: 8'

Missing Wall 7' X 8'
Missing Wall 5' 11 5/8" X 8'

Opens into FORMAL_DININ Opens into HALLWAY2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Wall							
101. Seal & paint crown molding - two coats	16.29 LF	1.25	0.24	4.12	24.72	(0.00)	24.72
Per Benjamin Moore Proper Application	includes; Clean Su	urface, Prime Surfac	ce, and Two C	oats Of Topcoa	at		
102. Clean the walls	130.33 SF	0.33	0.15	8.64	51.80	(0.00)	51.80
103. Seal the walls w/latex based stain blocker - one coat	130.33 SF	0.50	1.05	13.26	79.48	(0.00)	79.48
104. Paint the walls - two coats	130.33 SF	0.80	3.00	21.46	128.72	(0.00)	128.72
105. Paint door slab only - 2 coats (per side)	1.00 EA	30.60	0.78	6.28	37.66	(0.00)	37.66
106. Paint door or window opening - 2 coats (per side)	1.00 EA	25.52	0.47	5.20	31.19	(0.00)	31.19
107. Paint baseboard - two coats	16.29 LF	1.18	0.22	3.88	23.32	(0.00)	23.32
Floor							
108. Clean ceramic tile	52.22 SF	0.49	0.06	5.14	30.79	(0.00)	30.79
C-301RIDGECREST					7/	17/2021	Page:


4655 South Columbia Ave. Tulsa, OK 74105

Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

CONTINUED - Entry

DESCRIPTION	QUANTITY UNI	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV
109. Grout sealer	52.22 SF	0.89	0.96	9.50	56.94	(0.00)	56.94
110. Final cleaning - construction - Residential	52.22 SF	0.24	0.00	2.50	15.03	(0.00)	15.03
Totals: Entry			6.93	79.98	479.65	0.00	479.65



Formal Dining

557.89 SF Walls

841.28 SF Walls & Ceiling

31.60 SY Flooring

81.33 LF Ceil. Perimeter

Height: 8'

283.40 SF Ceiling 284.40 SF Floor

67.42 LF Floor Perimeter

Missing Wall - Goes to Floor 7' X 8' Opens into ENTRY2


Missing Wall - Goes to Floor 13' 11" X 6' 8" Opens into KITCHEN_DINI

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Wall							
111. Seal & paint crown molding - two coats	81.33 LF	1.25	1.22	20.58	123.46	(0.00)	123.46
Per Benjamin Moore Proper Application in	cludes; Clean S	urface, Prime Surfa	ce, and Two C	Coats Of Topco	oat		
112. Clean the walls	557.89 SF	0.33	0.64	36.94	221.68	(0.00)	221.68
113. Seal the walls w/latex based stain blocker - one coat	557.89 SF	0.50	4.49	56.70	340.14	(0.00)	340.14
114. Paint the walls - two coats	557.89 SF	0.80	12.83	91.82	550.96	(0.00)	550.96
115. Paint door or window opening - 2 coats (per side)	2.00 EA	25.52	0.93	10.38	62.35	(0.00)	62.35
116. Window blind - single cell - 7.1 to 14 SF	1.00 EA	28.79	0.00	5.76	34.55	(0.00)	34.55
117. Paint chair rail - two coats	67.42 LF	1.19	1.01	16.24	97.48	(0.00)	97.48
118. Paint baseboard - two coats	67.42 LF	1.18	0.93	16.10	96.59	(0.00)	96.59
Floor							
119. Final cleaning - construction - Residential	284.40 SF	0.24	0.00	13.66	81.92	(0.00)	81.92
Totals: Formal Dining	·		22.05	268.18	1,609.13	0.00	1,609.13

4655 South Columbia Ave. Tulsa, OK 74105

Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com



Kitchen/Dining Height: 8'

548.56 SF Walls 861.56 SF Walls & Ceiling 34.78 SY Flooring 80.17 LF Ceil. Perimeter 313.00 SF Ceiling313.00 SF Floor66.25 LF Floor Perimeter

Missing Wall - Goes to Floor

13' 11" X 6' 8"

Opens into FORMAL_DININ

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Ceiling							
120. 5/8" drywall - hung, taped, ready for texture	32.00 SF	2.13	2.21	14.06	84.43	(0.00)	84.43
121. Texture drywall - light hand texture	32.00 SF	0.47	0.18	3.04	18.26	(0.00)	18.26
122. Seal floor or ceiling joist system	32.00 SF	1.02	0.81	6.68	40.13	(0.00)	40.13
Per Benjamin Moore Proper Application in	cludes; Clean S	urface, Prime Sur	face, and Two	Coats Of Top	coat		
123. Clean the ceiling	313.00 SF	0.33	0.36	20.74	124.39	(0.00)	124.39
124. Seal the ceiling w/latex based stain blocker - one coat	313.00 SF	0.50	2.52	31.80	190.82	(0.00)	190.82
125. Paint the ceiling - two coats	313.00 SF	0.80	7.20	51.52	309.12	(0.00)	309.12
126. Light fixture	1.00 EA	50.26	0.00	10.06	60.32	(0.00)	60.32
127. Fluorescent light fixture - High grade	2.00 EA	72.96	0.00	29.18	175.10	(0.00)	175.10
128. Smoke detector	1.00 EA	48.65	0.00	9.74	58.39	(0.00)	58.39
Wall							
129. Crown molding - 3 1/4" MDF - w/detail	80.17 LF	3.15	0.18	50.54	303.26	(0.00)	303.26
130. Seal & paint crown molding - two	80.17 LF	1.25	1.20	20.28	121.69	(0.00)	121.69
coats		6 P. G	c 150	G . O.C.			
Per Benjamin Moore Proper Application in				•		(0.00)	217.07
131. Clean the walls	548.56 SF	0.33	0.63	36.32	217.97	(0.00)	217.97
132. Seal the walls w/latex based stain blocker - one coat	548.56 SF	0.50	4.42	55.74	334.44	(0.00)	334.44
133. Painting - Faux (special effects) - 2 part	548.56 SF	1.94	11.99	215.24	1,291.44	(0.00)	1,291.44
134. Paint door or window opening - 2 coats (per side)	4.00 EA	25.52	1.87	20.80	124.75	(0.00)	124.75
135. Window blind - single cell - 7.1 to 14 SF	1.00 EA	28.79	0.00	5.76	34.55	(0.00)	34.55
136. Paint door slab only - 2 coats (per side)	4.00 EA	30.60	3.11	25.10	150.61	(0.00)	150.61
137. Paint baseboard - two coats	66.25 LF	1.18	0.91	15.82	94.91	(0.00)	94.91
Floor							
138. Final cleaning - construction - Residential	313.00 SF	0.24	0.00	15.02	90.14	(0.00)	90.14
Totals: Kitchen/Dining			37.59	637.44	3,824.72	0.00	3,824.72
Total: 1st Floor			721.46	4,284.20	25,704.61	0.00	25,704.61

4655 South Columbia Ave.

Tulsa, OK 74105 Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

2nd Floor

5'9" 4'9"

5'5" 4'7" 5

2" 2mily Root 5

6'1 10'4" 5

6'1 10'4" 5

12'2" 16'5" 1

Family Room

700.31 SF Walls 1208.60 SF Walls & Ceiling 54.21 SY Flooring 95.94 LF Ceil. Perimeter 508.30 SF Ceiling 487.86 SF Floor

90.50 LF Floor Perimeter

Height: Attic


Missing Wall - Goes to Floor

4' 2" X 6' 8"

Opens into HALLWAY

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Wall							
Per Benjamin Moore Proper Application in	cludes; Clean S	urface, Prime Surfa	ce, and Two C	Coats Of Topco	oat		
139. Clean the walls	700.31 SF	0.33	0.81	46.38	278.29	(0.00)	278.29
140. Seal the walls w/latex based stain blocker - one coat	700.31 SF	0.50	5.64	71.16	426.96	(0.00)	426.96
141. Paint the walls - two coats	700.31 SF	0.80	16.11	115.28	691.64	(0.00)	691.64
142. Paint door or window opening - 2 coats (per side)	3.00 EA	25.52	1.40	15.60	93.56	(0.00)	93.56
143. Paint door slab only - 2 coats (per side)	2.00 EA	30.60	1.56	12.56	75.32	(0.00)	75.32
144. Window blind - single cell - 7.1 to 14 SF	2.00 EA	28.79	0.00	11.52	69.10	(0.00)	69.10
145. Paint baseboard - two coats	90.50 LF	1.18	1.25	21.62	129.66	(0.00)	129.66
Floor							
146. Carpet	487.86 SF	0.24	0.00	23.42	140.51	(0.00)	140.51
147. Carpet	563.08 SF	3.34	174.19	410.98	2,465.86	(0.00)	2,465.86
148. Carpet pad	487.86 SF	0.67	26.93	70.76	424.56	(0.00)	424.56
149. Final cleaning - construction - Residential	487.86 SF	0.24	0.00	23.42	140.51	(0.00)	140.51
Totals: Family Room		·	227.89	822.70	4,935.97	0.00	4,935.97

Hallway Height: 8'



444.99 SF Walls 565.78 SF Walls & Ceiling 13.42 SY Flooring 59.10 LF Ceil. Perimeter

120.79 SF Ceiling120.79 SF Floor54.93 LF Floor Perimeter

Missing Wall - Goes to Floor

4' 2" X 6' 8"

Opens into FAMILY_ROOM2

DESCRIPTION	QUANTITY UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV

Wall

4655 South Columbia Ave.

Tulsa, OK 74105 Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

CONTINUED - Hallway

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Per Benjamin Moore Proper Application in	cludes; Clean Su	rface, Prime Surfac	ce, and Two C	Coats Of Topco	oat		
150. Clean the walls	444.99 SF	0.33	0.51	29.48	176.84	(0.00)	176.84
151. Seal the walls w/latex based stain blocker - one coat	444.99 SF	0.50	3.58	45.22	271.30	(0.00)	271.30
152. Paint the walls - two coats	444.99 SF	0.80	10.24	73.24	439.47	(0.00)	439.47
153. Paint door or window opening - 2 coats (per side)	3.00 EA	25.52	1.40	15.60	93.56	(0.00)	93.56
154. Paint door slab only - 2 coats (per side)	2.00 EA	30.60	1.56	12.56	75.32	(0.00)	75.32
155. Window blind - single cell - 7.1 to 14 SF	2.00 EA	28.79	0.00	11.52	69.10	(0.00)	69.10
156. Paint baseboard - two coats	54.93 LF	1.18	0.76	13.12	78.70	(0.00)	78.70
Floor							
157. Carpet	120.79 SF	0.24	0.00	5.80	34.79	(0.00)	34.79
158. Carpet pad	120.79 SF	0.67	6.67	17.54	105.14	(0.00)	105.14
159. Carpet	189.83 SF	3.34	58.72	138.54	831.29	(0.00)	831.29
160. Final cleaning - construction - Residential	120.79 SF	0.24	0.00	5.80	34.79	(0.00)	34.79
Totals: Hallway			83.44	368.42	2,210.30	0.00	2,210.30



Bedroom 1 Height: 8'

413.33 SF Walls 560.67 SF Walls & Ceiling 16.37 SY Flooring

51.67 LF Ceil. Perimeter

147.33 SF Ceiling147.33 SF Floor51.67 LF Floor Perimeter

DESCRIPTION	QUANTITY UN	NIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Wall							
161. Paint door or window opening - 2 coats (per side)	2.00 EA	25.52	0.93	10.38	62.35	(0.00)	62.35
162. Paint door slab only - 2 coats (per side)	1.00 EA	30.60	0.78	6.28	37.66	(0.00)	37.66
163. Paint bifold door set - slab only - 2 coats (per side)	2.00 EA	41.08	3.03	17.04	102.23	(0.00)	102.23
164. Paint baseboard - two coats	51.67 LF	1.18	0.71	12.34	74.02	(0.00)	74.02
Floor							

4655 South Columbia Ave. Tulsa, OK 74105


Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

CONTINUED - Bedroom 1

DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV
165. Carpet	147.33 SF	0.24	0.00	7.08	42.44	(0.00)	42.44
166. Carpet pad	147.33 SF	0.67	8.13	21.36	128.20	(0.00)	128.20
167. Carpet	211.75 SF	3.34	65.51	154.56	927.32	(0.00)	927.32
168. Final cleaning - construction - Residential	147.33 SF	0.24	0.00	7.08	42.44	(0.00)	42.44
Totals: Bedroom 1			79.09	236.12	1,416,66	0.00	1.416.66

Closet 1 Height: 8'



154.67 SF Walls170.00 SF Walls & Ceiling1.70 SY Flooring19.33 LF Ceil. Perimeter

15.33 SF Ceiling15.33 SF Floor19.33 LF Floor Perimeter

DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Wall							
169. Paint door or window opening - 2 coats (per side)	1.00 EA	25.52	0.47	5.20	31.19	(0.00)	31.19
170. Paint bifold door set - slab only - 2 coats (per side)	2.00 EA	41.08	3.03	17.04	102.23	(0.00)	102.23
171. Paint baseboard - two coats	19.33 LF	1.18	0.27	4.62	27.70	(0.00)	27.70
Floor							
172. Carpet	15.33 SF	0.24	0.00	0.74	4.42	(0.00)	4.42
173. Carpet pad	15.33 SF	0.67	0.85	2.22	13.34	(0.00)	13.34
174. Carpet	71.75 SF	3.34	22.20	52.38	314.23	(0.00)	314.23
175. Final cleaning - construction - Residential	15.33 SF	0.24	0.00	0.74	4.42	(0.00)	4.42
Totals: Closet 1			26.82	82.94	497.53	0.00	497.53

4655 South Columbia Ave.

Tulsa, OK 74105 Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com



Bedroom 2 Height: 8'

> 413.33 SF Walls 579.33 SF Walls & Ceiling


18.44 SY Flooring 51.67 LF Ceil. Perimeter

51.67 LF Floor Perimeter

166.00 SF Ceiling

166.00 SF Floor

DESCRIPTION	QUANTITY U	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Wall							
176. Paint door or window opening - 2 coats (per side)	2.00 EA	25.52	0.93	10.38	62.35	(0.00)	62.35
177. Paint door slab only - 2 coats (per side)	1.00 EA	30.60	0.78	6.28	37.66	(0.00)	37.66
178. Paint bifold door set - slab only - 2 coats (per side)	2.00 EA	41.08	3.03	17.04	102.23	(0.00)	102.23
179. Paint baseboard - two coats	51.67 LF	1.18	0.71	12.34	74.02	(0.00)	74.02
Floor							
180. Carpet	166.00 SF	0.24	0.00	7.96	47.80	(0.00)	47.80
181. Carpet pad	166.00 SF	0.67	9.16	24.08	144.46	(0.00)	144.46
182. Carpet	223.25 SF	3.34	69.06	162.96	977.68	(0.00)	977.68
183. Final cleaning - construction - Residential	166.00 SF	0.24	0.00	7.96	47.80	(0.00)	47.80
Totals: Bedroom 2			83.67	249.00	1,494.00	0.00	1,494.00



Closet 2 Height: 8'

124.56 SF Walls

136.13 SF Walls & Ceiling

1.29 SY Flooring

15.57 LF Ceil. Perimeter

11.57 SF Ceiling

11.57 SF Floor

15.57 LF Floor Perimeter

DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Wall							
184. Paint door or window opening - 2 coats (per side)	1.00 EA	25.52	0.47	5.20	31.19	(0.00)	31.19
185. Paint bifold door set - slab only - 2 coats (per side)	2.00 EA	41.08	3.03	17.04	102.23	(0.00)	102.23
186. Paint baseboard - two coats	15.57 LF	1.18	0.22	3.72	22.31	(0.00)	22.31
Floor							
187. Carpet	11.57 SF	0.24	0.00	0.56	3.34	(0.00)	3.34
188. Carpet pad	11.57 SF	0.67	0.64	1.68	10.07	(0.00)	10.07
189. Carpet	68.08 SF	3.34	21.06	49.70	298.15	(0.00)	298.15
VC-301RIDGECREST					7/	17/2021	Page: 13

4655 South Columbia Ave. Tulsa, OK 74105

Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

CONTINUED - Closet 2

DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV
190. Final cleaning - construction - Residential	11.57 SF	0.24	0.00	0.56	3.34	(0.00)	3.34
Totals: Closet 2			25.42	78.46	470.63	0.00	470.63



Master Bedroom Height: 8'

562.67 SF Walls 871.84 SF Walls & Ceiling 34.35 SY Flooring 70.33 LF Ceil. Perimeter 309.17 SF Ceiling 309.17 SF Floor 70.33 LF Floor Perimeter

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Wall							
191. 1/2" - drywall per LF - up to 4' tall	12.00 LF	13.23	2.97	32.34	194.07	(0.00)	194.07
Per Benjamin Moore Proper Application in	cludes; Clean S	urface, Prime Surfa	ce, and Two C	oats Of Topcoa	at		
192. Clean the walls	562.67 SF	0.33	0.65	37.28	223.61	(0.00)	223.61
193. Seal the walls w/latex based stain blocker - one coat	562.67 SF	0.50	4.53	57.16	343.03	(0.00)	343.03
194. Paint the walls - two coats	562.67 SF	0.80	12.94	92.60	555.68	(0.00)	555.68
195. Casing - 2 1/4"	21.00 LF	2.41	2.68	10.66	63.95	(0.00)	63.95
196. Paint door or window opening - 2 coats (per side)	5.00 EA	25.52	2.33	25.98	155.91	(0.00)	155.91
197. Paint door slab only - 2 coats (per side)	3.00 EA	30.60	2.34	18.82	112.96	(0.00)	112.96
198. Paint bifold door set - slab only - 2 coats (per side)	1.00 EA	41.08	1.51	8.52	51.11	(0.00)	51.11
199. Window blind - single cell - 7.1 to 14 SF	2.00 EA	28.79	0.00	11.52	69.10	(0.00)	69.10
200. Baseboard - 3 1/4"	70.33 LF	3.30	9.95	48.42	290.46	(0.00)	290.46
201. Paint baseboard - two coats	70.33 LF	1.18	0.97	16.80	100.76	(0.00)	100.76
Floor							
202. Sheathing - plywood - 3/4" - tongue and groove	32.00 SF	5.43	11.48	37.06	222.30	(0.00)	222.30
203. Screw down existing subfloor - eliminate floor squeaks	309.17 SF	0.64	3.20	40.22	241.29	(0.00)	241.29
204. Seal & paint plywood sheathing	309.17 SF	0.74	6.40	47.04	282.23	(0.00)	282.23
205. Carpet	309.17 SF	0.24	0.00	14.84	89.04	(0.00)	89.04

4655 South Columbia Ave. Tulsa, OK 74105 Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

CONTINUED - Master Bedroom

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
206. Carpet pad	309.17 SF	0.67	17.07	44.84	269.06	(0.00)	269.06
207. Carpet	379.17 SF	3.34	117.30	276.74	1,660.47	(0.00)	1,660.47
208. Final cleaning - construction - Residential	309.17 SF	0.24	0.00	14.84	89.04	(0.00)	89.04
Totals: Master Bedroom		·	196.32	835.68	5,014.07	0.00	5,014.07

General

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
2.5 months							
209. Temporary toilet (per month)	5.00 MO	203.61	0.00	203.62	1,221.67	(0.00)	1,221.67
210. Temporary hand washing station (per month)	2.50 MO	240.00	0.00	120.00	720.00	(0.00)	720.00
211. Temporary power usage (per month)	2.50 MO	126.54	36.38	70.56	423.29	(0.00)	423.29
212. Dumpster load - Approx. 30 yards, 5-7 tons of debris	2.00 EA	542.00	0.00	216.80	1,300.80	(0.00)	1,300.80
Progressive Cleanup and Traffic Control	l						
213. General Laborer - per hour	55.00 HR	38.64	0.00	425.04	2,550.24	(0.00)	2,550.24
214. Residential Supervision / Project Management - per hour	55.00 HR	63.74	0.00	701.14	4,206.84	(0.00)	4,206.84
Life and Safety							
215. Hand Sanitizer Station 1 Per Floor	2.50 MO	68.50	0.00	34.26	205.51	(0.00)	205.51
Below Mask is Two Change outs Per Perso	n Per Working D	ay					
216. Personal protective mask	440.00 EA	1.19	0.00	104.72	628.32	(0.00)	628.32
Same Math Applies							
217. Personal protective gloves - Disposable (per pair)	440.00 EA	1.19	0.00	104.72	628.32	(0.00)	628.32
218. Job-site cargo/storage container - 20' long - per month	2.50 MO	112.00	32.20	62.44	374.64	(0.00)	374.64
219. Job-site moving container - pick up/del. (ea. way) 12'-20'	2.00 EA	92.75	0.00	37.10	222.60	(0.00)	222.60
Totals: General			68.58	2,080.40	12,482.23	0.00	12,482.23
Total: 2nd Floor			791.23	4,753.72	28,521.39	0.00	28,521.39
Line Item Totals: VC-301RIDGECRES	Γ		4,786.17	24,166.94	186,263.01	0.00	186,263.01

4655 South Columbia Ave. Tulsa, OK 74105 Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

Grand Total Areas:

4,969.33	SF Walls	2,495.34	SF Ceiling	7,464.67	SF Walls and Ceiling
2,475.90	SF Floor	275.10	SY Flooring	618.79	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	656.23	LF Ceil. Perimeter
2,475.90	Floor Area	2,661.98	Total Area	5,130.66	Interior Wall Area
4,122.40	Exterior Wall Area	462.68	Exterior Perimeter of		
			Walls		
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	0.00	Total Hip Length		

Coverage	Item Total	%	ACV Total	%
Dwelling	150,694.92	80.90%	150,694.92	80.90%
Other Structures	35,568.09	19.10%	35,568.09	19.10%
Contents	0.00	0.00%	0.00	0.00%
Total	186,263.01	100.00%	186,263.01	100.00%

4655 South Columbia Ave. Tulsa, OK 74105 Phone | 972.266.4950 Email | Brook@claimadvisorsllc.com

Summary for Dwelling

Line Item Total	126,748.86
Material Sales Tax	3,791.26
Storage Rental Tax	32.20
Subtotal	130,572.32
Overhead	10,061.30
Profit	10,061.30
Replacement Cost Value	\$150,694.92
Net Claim	\$150,694.92

Matt Clark Estimator

4655 South Columbia Ave. Tulsa, OK 74105 Phone | 972.266.4950 Email | Brook@claimadvisorsllc.com

Summary for Other Structures

Line Item Total	30,561.04
Material Sales Tax	962.71
Subtotal	31,523.75
Overhead	2,022.17
Profit	2,022.17
Replacement Cost Value	\$35,568.09
Net Claim	\$35,568.09

Matt Clark Estimator

4655 South Columbia Ave. Tulsa, OK 74105 Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

Recap by Room

nate: VC-301RIDGECREST			
Roof		13,774.90	8.76%
Coverage: Dwelling	100.00% =	13,774.90	62.400 /
Exterior	40.40	99,859.61	63.48%
Coverage: Dwelling	69.40% =	69,298.57	
Coverage: Other Structures	30.60% =	30,561.04	
: 1st Floor			
Living Room		8,034.49	5.11%
Coverage: Dwelling	100.00% =	8,034.49	
DIning Area		5,581.72	3.55%
Coverage: Dwelling	100.00% =	5,581.72	
Hallway		2,221.41	1.41%
Coverage: Dwelling	100.00% =	2,221.41	
Entry		392.74	0.25%
Coverage: Dwelling	100.00% =	392.74	
Formal Dining		1,318.90	0.84%
Coverage: Dwelling	100.00% =	1,318.90	
Kitchen/Dining		3,149.69	2.00%
Coverage: Dwelling	100.00% =	3,149.69	
Area Subtotal: 1st Floor		20,698.95	13.16%
Coverage: Dwelling	100.00% =	20,698.95	
: 2nd Floor			
Family Room		3,885.38	2.47%
Coverage: Dwelling	100.00% =	3,885.38	
Hallway		1,758.44	1.12%
Coverage: Dwelling	100.00% =	1,758.44	
Bedroom 1		1,101.45	0.70%
Coverage: Dwelling	100.00% =	1,101.45	
Closet 1		387.77	0.25%
Coverage: Dwelling	100.00% =	387.77	
Bedroom 2		1,161.33	0.74%
Coverage: Dwelling	100.00% =	1,161.33	
Closet 2		366.75	0.23%
Coverage: Dwelling	100.00% =	366.75	
Master Bedroom		3,982.07	2.53%
Coverage: Dwelling	100.00% =	3,982.07	
General		10,333.25	6.57%
Coverage: Dwelling	100.00% =	10,333.25	

4655 South Columbia Ave. Tulsa, OK 74105 Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com

Area Subtotal: 2nd Floor Coverage: Dwelling	100.00% =	22,976.44 22,976.44	14.61%
Subtotal of Areas		157,309.90	100.00%
Coverage: Dwelling	80.57% =	126,748.86	
Coverage: Other Structures	19.43% =	30,561.04	
			
Total		157,309.90	100.00%

4655 South Columbia Ave. Tulsa, OK 74105 Phone | 972.266.4950

Email | Brook@claimadvisorsllc.com


Recap by Category

O&P Items			Total	%
CLEANING			2,728.36	1.46%
Coverage: Dwelling	@	100.00% =	2,728.36	
CONT: PACKING, HANDLNG, STORAGE			465.50	0.25%
Coverage: Dwelling	@	100.00% =	465.50	
GENERAL DEMOLITION			15,107.46	8.11%
Coverage: Dwelling	@	58.68% =	8,865.12	
Coverage: Other Structures	@	41.32% =	6,242.34	
DOORS			2,602.70	1.40%
Coverage: Dwelling	@	100.00% =	2,602.70	
DRYWALL			2,699.08	1.45%
Coverage: Dwelling	@	100.00% =	2,699.08	
ELECTRICAL			48.65	0.03%
Coverage: Dwelling	@	100.00% =	48.65	
ELECTRICAL - SPECIAL SYSTEMS			586.65	0.31%
Coverage: Dwelling	@	100.00% =	586.65	
FLOOR COVERING - CARPET			7,826.03	4.20%
Coverage: Dwelling	@	100.00% =	7,826.03	
FLOOR COVERING - CERAMIC TILE			46.48	0.02%
Coverage: Dwelling	@	100.00% =	46.48	
FLOOR COVERING - WOOD			2,611.54	1.40%
Coverage: Dwelling	@	100.00% =	2,611.54	
FENCING			13,016.70	6.99%
Coverage: Other Structures	@	100.00% =	13,016.70	
FINISH CARPENTRY / TRIMWORK			1,253.95	0.67%
Coverage: Dwelling	@	100.00% =	1,253.95	
FRAMING & ROUGH CARPENTRY			333.55	0.18%
Coverage: Dwelling	@	100.00% =	333.55	
HAZARDOUS MATERIAL REMEDIATION			1,047.20	0.56%
Coverage: Dwelling	@	100.00% =	1,047.20	
INSULATION			3,643.90	1.96%
Coverage: Dwelling	@	100.00% =	3,643.90	
LABOR ONLY			5,630.90	3.02%
Coverage: Dwelling	@	100.00% =	5,630.90	
LIGHT FIXTURES			926.48	0.50%
Coverage: Dwelling	@	100.00% =	926.48	
MASONRY			6,946.50	3.73%
Coverage: Dwelling	@	100.00% =	6,946.50	20.070
PAINTING			10,957.03	5.88%
Coverage: Dwelling	@	100.00% =	10,957.03	2.30,0
ROOFING			11,830.85	6.35%
	_	100.000/		0.00 / 0
Coverage: Dwelling	@	100.00% =	11,830.85	

4655 South Columbia Ave. Tulsa, OK 74105 Phone | 972.266.4950


Email | Brook@claimadvisorsllc.com

O&P Items			Total	%
SIDING			16,149.36	8.67%
Coverage: Dwelling	@	100.00% =	16,149.36	
SOFFIT, FASCIA, & GUTTER			5,786.18	3.11%
Coverage: Dwelling	@	100.00% =	5,786.18	
TILE			1,350.72	0.73%
Coverage: Dwelling	@	100.00% =	1,350.72	
TEMPORARY REPAIRS			2,105.65	1.13%
Coverage: Dwelling	@	100.00% =	2,105.65	
WINDOW TREATMENT			345.48	0.19%
Coverage: Dwelling	@	100.00% =	345.48	
O&P Items Subtotal			116,046.90	62.30%
Non-O&P Items			Total	%
FRAMING & ROUGH CARPENTRY			29,961.00	16.09%
Coverage: Dwelling	@	100.00% =	29,961.00	
SWIMMING POOLS & SPAS			11,302.00	6.07%
Coverage: Other Structures	@	100.00% =	11,302.00	
Non-O&P Items Subtotal			41,263.00	22.15%
O&P Items Subtotal			116,046.90	62.30%
Material Sales Tax			4,753.97	2.55%
Coverage: Dwelling	@	79.75% =	3,791.26	
Coverage: Other Structures	@	20.25% =	962.71	
Storage Rental Tax			32.20	0.02%
Coverage: Dwelling	@	100.00% =	32.20	
Overhead			12,083.47	6.49%
Coverage: Dwelling	@	83.26% =	10,061.30	
Coverage: Other Structures	@	16.74% =	2,022.17	
Profit			12,083.47	6.49%
Coverage: Dwelling	@	83.26% =	10,061.30	
Coverage: Other Structures	@	16.74% =	2,022.17	
Total			186,263.01	100.00%





1st Floor





2nd Floor